

## Connecting Scale to PC/Laptop (Scale App Setup)

The G6 fitted with the Serial Interface port, is designed to work with a laptop or PC running Microsoft Windows 10 or 11 Operating System.



The connection between the scale and the computer is made via a Serial to USB converter cable. (Provided).

1. Insert the Serial end of the converter cable to the scales serial port.
2. Use the locking screws to secure the cable in place.
3. Insert the USB end of the converter cable to a USB port of the Laptop/PC.

